



T500W2G27P Adapter Field Test

(PC Only) Install the Windows driver from the Thrustmaster website. Open the Thrustmaster calibration utility.


Power up the wheel and test the original Thrustmaster pedals to be sure everything is working correctly.

Plug the adapter into the wheel. Do not plug the Logitech pedals into the adapter.


Use a short wire or a bent paper clip and insert into the different combinations shown below. You should get the results shown below.




GAS 100%




GAS 0%




GAS 0%




BRAKE 100%




BRAKE 0%




BRAKE 0%




CLUTCH 100%




CLUTCH 0%



CLUTCH 0%



DO NOT DO THIS



DO NOT DO THIS